## FEDERAL COMMUNICATIONS COMMISSION 445 TWELFTH STREET SW WASHINGTON DC 20554

MEDIA BUREAU
AUDIO DIVISION
APPLICATION STATUS: 120

APPLICATION STATUS: (202) 418-2730 HOME PAGE: www.fcc.gov/mb/audio/

ENGINEER: CHARLES N. (NORM) MILLER
TELEPHONE: (202) 418-2767

FACSIMILE: (202) 418-1410 E-MAIL: charles.miller@fcc.gov

July 14, 2008

Stephen T. Yelverton, Esq. 601 Pennsylvania Avenue NW, Suite 900 South Washington, DC 20004

Re: Monroe Broadcasting Company, Inc.

WIXE (AM), Monroe, North Carolina Facility Identification Number: 43533

Special Temporary Authority

## Dear Counsel:

This is in reference to the request filed July 11, 2008, on behalf of Monroe Broadcasting Company, Inc. ("MBC"). MBC requests special temporary authority ("STA") to operate Station WIXE with emergency antenna facilities pursuant to Section 73.1680. In support of the request, MBC states that, on July 10, 2008, the WIXE tower collapsed following the collision of a vehicle with one of the tower's guy anchors. MBC states that it has restored operation with an emergency wire dipole antenna at the licensed site.

Section 73.1680 of the Commission's rules provides for operation with emergency antenna facilities following damage to authorized antenna systems, provided that an informal request for continued use of an emergency antenna is filed with the Commission within 24 hours. In particular, Section 73.1680(b)(1) provides that AM stations may use a horizontal or vertical wire as an emergency antenna.

Our review indicates that the request complies with Section 73.1680.

Accordingly, the request for STA IS HEREBY GRANTED. Station WIXE may continue to operate with emergency antenna facilities as described above. It will be necessary to further reduce power or cease operation if complaints of interference are received. MBC must notify the Commission when licensed operation is restored.<sup>2</sup> MBC must use whatever means are necessary to protect workers and the public from exposure to radio frequency radiation in excess of the Commission's exposure guidelines. *See* 47 CFR § 1.1310.

WIXE is licensed for operation on 1190 kHz with 5 kilowatts daytime and 0.07 kilowatt nighttime, employing a nondirectional antenna (ND-2-U).

<sup>&</sup>lt;sup>2</sup> See 47 CFR §§ 73.45(c), 73.51, 73.54, 73.61(b).

This authority expires on January 14, 2009.

STA Advisory: Section 309(f) of the Communications Act of 1934, as amended, authorizes the Commission to grant STA in cases of "extraordinary circumstances requiring temporary authorizations in the public interest and when delay in the institution of the temporary operations would seriously prejudice the public interest." However, Section 309(f) is not a means by which a licensee/permittee may circumvent established processing procedures which require the filing of an application, nor is it a means by which a broadcaster may enhance his facility or make operation more convenient for the broadcaster. Stations operating with less than licensed facilities under temporary authorities can be viewed as receiving the benefit of a larger protection area than that in which they are currently providing service.

Accordingly, Special Temporary Authorities by nature are to be temporary and are not intended for extended use. Licensees of stations operating under temporary authorities are reminded that timely restoration of permanent facilities is the responsibility of the licensee and should be undertaken expeditiously. Any request for extension of special temporary authorities carries an increased burden with each subsequent request.

Therefore, requests for extension of STA will be granted only where the licensee can show that one or more of the following criteria have been met:

- Restoration of licensed facilities is complete and testing is underway;
- Substantial progress has been made during the most recent STA period toward restoration of licensed operation; or
- No progress has been made during the most recent STA period for reasons clearly beyond the licensee's control, and the licensee has taken all possible steps to expeditiously resolve the problem.

Sincerely,

Charles N. Miller, Engineer

Audio Division Media Bureau

cc: Monroe Broadcasting Company, Inc.